



202490-087400T






Fig. 2.




Fig. 3.




Fig. 5A.




Fig. 4A.




Fig. 4B.




Fig. 5B.

Fig. 7.







Fig. 6.






Fig. 10C.




Fig. 10D.




Fig. 11.




Fig. 12.

20250708T1400T




Fig. 13.




Fig. 17.

LOSS dB






Fig. 18.






Fig. 19A.




Fig. 19B.




Fig. 19C.




Fig. 19D.




Fig. 19E.




Fig. 19F.




Fig. 19G.




Fig. 19H.




Fig. 19I.




Fig. 19J.




Fig. 19K.




Fig. 19L.